

## Release Notes

---

### Model: KMU-100

---

Mar 28, 2017 Main Board Unit

1. User Interface software:

Version: 1.0.13932

File name: DVLinkInstaller32\_2017\_03\_13\_13932

2. Firmware (ARM/FPGA/NIOS)

Version: ARM: 000134E7 / FPGA: 0100006A / NIOS: 000133C3

File name: kmu\_100\_134E7\_006A\_133C3.dv kf

#### Issues

1. Corrected values for vertical positions.
  2. Added the Default Positions button which restores default position for all frames.
- 

Feb 13, 2017 Main Board Unit

1. User Interface software:

Version: 1.0.13021

File name: DVLinkInstaller32\_2016\_11\_23\_13021

2. Firmware (ARM/FPGA/NIOS)

Version: ARM: 000134E7 / FPGA: 0100006A / NIOS: 000133C3

File name: kmu\_100\_134E7\_006A\_133C3.dv kf

#### Issues

1. Added ISP programming mode to ARM, which requires short pressing RESET button to enter this mode. RED/GREEN LEDs near ARM flash alternately in this mode
- 

Dec 21, 2016 Main Board Unit

1. User Interface software:

Version: 1.0.13021

File name: DVLinkInstaller32\_2016\_11\_23\_13021

2. Firmware (ARM/FPGA/NIOS)

Version: ARM: 000132E0 / FPGA: 0100006A / NIOS: 000133C3

File name: kmu\_100\_32e0\_006A\_33c3

**Issues**

1. Corrected HDMI YUV output format supported by TLM-170
  2. Corrected HDMI output audio
  3. Corrected SDI embedded audio output
-